


+

1/41



+




FIG. 2

205210" 214/5001




FIG. 3




FIG. 4




FIG. 5

5/41




FIG. 6




FIG. 7

FIG. 8

10057412.012502




FIG. 9A




FIG. 10A




FIG. 9B




FIG. 10B

205210 24425001

+




FIG. 13




FIG. 12A




FIG. 12B




FIG. 11A




FIG. 11B

+




FIG. 14




FIG. 15

2025742.01302




FIG. 16

10057412.012502




FIG. 17A




FIG. 17B






FIG. 17C






FIG. 20A




FIG. 20B




FIG. 25

202210242500F




FIG. 21




FIG. 22




FIG. 23

205210" 21425001





FIG. 24






FIG. 27A




FIG. 27B




FIG. 27C




FIG. 28





FIG. 29

+



+




FIG. 31A




FIG. 31B




FIG. 32A




FIG. 32B




FIG. 32C




FIG. 33A




FIG. 33B

10057412.012502




FIG. 33C




FIG. 33D




FIG. 33E

2057432 214/502




FIG. 34A




FIG. 34B




FIG. 34C




FIG. 35A




FIG. 35B




FIG. 35C




FIG. 36A




FIG. 36B

10057412.012503 20251024 214500T

+




FIG. 37A




FIG. 37B

+

+




FIG. 38A




FIG. 38B

+




FIG. 39A

10057412.012502




FIG. 39B




FIG. 39C




FIG. 39D




FIG. 40A




FIG. 40B




FIG. 40C




FIG. 41A




FIG. 41B




FIG. 41C

205210" 2142500T




FIG. 42A




FIG. 42B




FIG. 43A




FIG. 43B




FIG. 44

10057412.012502




Fig. 45A

20257412.012502




Fig. 45B

20221012 105741Z




Fig. 45C

10057412.012502
205210.2142501




Fig. 46

205210" 214/5091






Fig. 47






FIG. 48C




FIG. 48D




FIG. 48E




FIG. 49A







FIG. 49B



10657412.013502




FIG. 51




FIG. 52A




FIG. 52B




Fig. 53A

205210" 214/25001




Fig. 53B

205210" 214/500"




Fig. 54A

105743.01302




Fig. 54B

20057412.013502




Fig. 55A

205210" 21475001




Fig. 55B




FIG. 56A




FIG. 56B




FIG. 56C




FIG. 56D




FIG. 56E




FIG. 57A




FIG. 57B




FIG. 57C




FIG. 57D




FIG. 58A




FIG. 58B




FIG. 58C




FIG. 59




FIG. 60






FIG. 61



10057412.012502
2022102445001




FIG. 63




Fig. 64